

**ORC Water Professionals
Operations Report
November 2015
Prepared by:
Gabrielle Begeman, Operations and Compliance Manager**

Hi-Land Acres Water and Sanitation District

North Well

- The chlorine ejector had to be rebuilt. Parts were purchased and the repair was made. The chlorinator is now operational.
- Outstanding items:
 - The vegetation surrounding the water treatment plant is in need of mowing, weed trimming.
 - ORC was informed that the south fencing surrounding the North Well will need to be moved back 4 feet for Electrical Safety Requirements (ESR). This will safely allow certified persons to access the main disconnect box. Minimum safe distance is 4 feet from panel door opening.

South Well

- Outstanding items:
 - The vegetation surrounding the water treatment plant and access paths are in need of mowing, weed trimming and debris removal.

WTP & Distribution System

- The meter readings were sent to AMCOBI on 11-2- 2015.
- All hydrants have been flushed, exercised and maintained. Hydrant isolation valves have been exercised.

WWTP & Collection System

- There are still 3 remaining intruding taps that are either not accessible to have cut out, or are not creating any adverse conditions to warrant cutting them out. These were mentioned in the previous operations report.