

ORC Water Professionals

Operations Report

December 2015

Prepared by:

John Nyman, Operator in Responsible Charge

Hi-Land Acres Water and Sanitation District

North Well

The well pump was malfunctioning due to an electrical imbalance detected by the Motor Minder. A technician from Boulder Well Service came out and searched for a short in the system. He was unable to find a short but reset the parameters on the motor minder and the well pump is now operational.

Outstanding items:

South fencing surrounding the North Well will need to be moved back 4 feet for Electrical Safety Requirements (ESR). This will safely allow certified persons to access the main disconnect box. Minimum safe distance is 4 feet from panel door opening.

South Well

Mowing was done and it looks like they did a pretty good job overall.

Outstanding items:

No outstanding items.

WTP & Distribution System

The meter readings were sent to AMCOBI on 12-2- 2015.

WWTP & Collection System

No action shall be taken regarding 3 remaining intruding taps as they are not creating any adverse conditions to warrant cutting them out.