

ORC Water Professionals
Operations Report
January 2016
Prepared by:
John Nyman, Operator in Responsible Charge
Hi-Land Acres Water and Sanitation District

North Well

□

During the second half of December we had some high CL2 levels at the north well. There seems to be a back pressure event whereby the North well will inject CL2 when the well is not running. Gabby and I have discussed a solution and should be installing a new check valve to prevent these occurrences in the future.

□

Outstanding items:

South fencing surrounding the North Well will need to be moved back 4 feet for Electrical Safety Requirements (ESR). This will safely allow certified persons to access the main disconnect box. Minimum safe distance is 4 feet from panel door opening.

South Well

We have seen intermittent feed problems with the CL2 ejector. I have discussed a solution to this challenge with Gabby and we intend to implement a solution (another check valve and re piping part of the ejector array. This should be a low cost solution.

Outstanding items:

No outstanding items.

WTP & Distribution System

Possible leak at 9987 E 159th Ave. JN has contacted owner and will make an appointment to trouble shoot the possible leak

The meter readings were sent to AMCOBI on 12-31-2015

WWTP & Collection System

I have been pulling a lot of rags out of the Influent Channel. These are not biodegradable and should not be flushed period. Someone should write a letter to the day care center to make sure they are informed about this.