

Hi-Land Acres Water and Sanitation District

North Well

- Tank level within normal range for the month.
- The flow meter isn't operational. It was taken apart and cleared of iron bacteria and replaced. It is still not functional.
- The demand for chlorine increased in the well water resulting in a lower residual than normal. This may have prompted complaints of smelly water.
- Purchased new lock for tank hatch

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- Replaced air compressor for surge tank and replaced lines and fittings. The new compressor will help correct issues with pressure and excess air in the system.

Distribution System

- Normal operations
- Bacteriological sampling collected and passed.
- Flushed several hydrants on north and south side while troubleshooting issues with chlorine demand and odor reports