

### **Hi-Land Acres Water and Sanitation District**

#### **North Well**

- Tank level within normal range for the month.
- The flow meter was able to be repaired. Eventually an electromagnetic flow meter would be recommended.
- The timer for the booster pumps needed to be adjusted. Pumps should have been automatically cycling when system pressure dropped to 40psi but were not. They are now operating normally.

#### **South Well**

- Normal operation without any difficulties.
- Tank level within normal range for the month.

#### **Distribution System**

- Normal operations
- Bacteriological sampling collected and passed.