

Hi-Land Acres Water and Sanitation District

North Well

- Tank level within normal range for the month.
- Normal operation of the well and booster pumps.
- The booster pumps are making quite a bit of noise and should be looked at by a pump company.
- Please consider the revised quote from Viking for installation of the guard rail system to access the tank. The hot work will necessitate draining the tank and spot fixing the interior bubbling of the coating. This is included in the cost for the guard rails. I have not received any other quotes.
- Welgicide cleaner has been offered as a potential solution to clean the iron bacteria from the well. ORC can procure and facilitate the application of this cleaner per the manufacturers recommendations for time and materials expense. I have been able to locate a vendor but do not yet have pricing.
- The booster pumps are 15 HP and the VFD's that I have for use are only rated for 7.5 HP. New 15 HP VFD's could likely be sourced for approximately \$5000 each.

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.

Distribution System

- Normal operations
- Bacteriological sampling collected and passed.
- Replaced meter for 9910 E 157th Ave due to inactivity during meter readings.