

ORC Water Professionals
Operations Report
November 2025
Prepared by: Gabrielle Begeman and Tim Schneider

Hi-Land Acres Water and Sanitation District

North Well

- Bad phase switch causing irregular well pump functions replaced.

South Well

- Welded tank leaking pipe work continuing. Pipe lined with fiberglass and being prepped for an additional epoxy coating

Distribution System

- Meter reads completed