

Hi-Land Acres Water and Sanitation District

North Well

- Overflow on North tank was tested and flowed very well to the appropriate drainage point.
- The North tank has been put back online after the well was disinfected and flushed.
- The North Well video can be found here:
<https://www.dropbox.com/sh/anwej6fcfefwlo7/AAA4P5f15iHqvF6eagvSnOw3a?dl=0>
- Instantaneous flowrates from the North Well are 40gpm
- The North tank is still in need of a sand and recoat. Please see the attached bids.

South Well

- South well has been overflowing slightly and is in need of new probes. Browns Hill Engineering has been brought in to assess the needs of the system to address the fire flows and tank controls.