

Hi-Land Acres Water and Sanitation District

North Well

- North well is not in use currently.
- The tank is full of water that was brought over from the south well through the distribution system. This water was re-chlorinated before entering the tank.
- Coal Creek Excavating investigated the broken pipe and found that the pipe was missing entirely from the valve to the overflow/drain piping. See the photo. This pipe was replaced and run to the overflow pipe.
- A collection drain was also installed to facilitate adequate drainage to the surrounding building area.
- The end of the drain pipe was extended and daylighted.
- Both booster pumps have been removed and taken to the motor shop for repair. One is getting a new mechanical seal and the other is getting the motor rewound.

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- With North well turned off, the South well is handling all distribution usage needs.

Distribution System

- Normal operations
- Bacteriological sampling collected and passed.