

Hi-Land Acres Water and Sanitation District

North Well

- North tank has been refilled with north well water.
- The north well is designated as emergency status and was shut down the first week of September when the tank levels had been stabilized.
- To return this well to permanent status, it would need to be sampled submitted to the State health department and utilized routinely.
- The booster pump controls should be upgraded to enable alternation, better cycling and to eliminate the outdated equipment unintended for operation for the booster pumps via a constant pressure system that was installed back in January. This has been discussed with both Boulder Water Well and Applied Ingenuity in an attempt to provide a recommendation on a path to move forward.

South Well

- Tank level indicator continues to show problems as the level reported is sporadic making actual tank level within a range of 2-5' of what is being indicated.

Distribution System

- The meter reading equipment has failed and meters have been estimated again for this month. A new program and computer has been ordered and is in the works for installation to collect the reads through Beacon AMA.