

Hi-Land Acres Water and Sanitation District

North Well

- North well is not in use currently
- One of the boosters was found to have a leaky seal. It was isolated and will be serviced.
- The other booster would not run. We have initiate Boulder Water Well to investigate.

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- With North well turned off, the South well is handling all distribution usage needs.

Distribution System

- Normal operations
- Bacteriological sampling collected and passed.

Collections System

- Sewer line at E 159th Pl reported blockage and backup. We inspected and found the mainline partially blocked. ORC brought out Guildner Pipeline who cleaned and cleared the blockage. They mentioned that the line was really dirty and lots of debris was sitting within the line due to the limited slope. They suggested that the mains be cleaned to avoid blockage and backups. I believe it has been many years since the last cleaning and the system is likely due.