

Hi-Land Acres Water and Sanitation District

North Well

- North well is not in use currently.
- The tank is full of water that was brought over from the south well through the distribution system. This water was re-chlorinated before entering the tank.
- Both booster pumps have attempted to be bled of air and started. ORC was unsuccessful in getting the booster pumps online. ORC will attempt again to bring the boosters online.
- Boulder Water Well was approached to provide an estimate for installing VFD's on all booster pumps to maintain constant pressure. We are awaiting a quote from them.
- Boulder Water Well was approached to provide an estimate for performing the well tasks as suggested by Water Systems Engineering. We are awaiting a quote from them.

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- With North well turned off, the South well is handling all distribution usage needs.

Distribution System

- Normal operations
- Bacteriological sampling collected and passed.