

Hi-Land Acres Water and Sanitation District

North Well

- North tank is now in use currently. Being filled with water and chlorinated from the south well.
- Installed an automatic solenoid valve on a timer so the tank doesn't overflow.
- The meter was moved to the line filling the north tank so we can track the flow going in the north tank from the south tank.

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- Handling the flow needed to fill the north tank with no problems.

Distribution System

- Having the same problem with the meter reading equipment is out of date. We are unable to collect the reads some months as the system is utilizing a computer that is no longer supported by Windows. Badger meter is recommending replacement of the radio endpoints with cellular endpoints to be read cellularly and uploaded to the cloud. See information here:

<https://www.badgermeter.com/products/endpoints/orion-cellular-endpoints/>