

## **Hi-Land Acres Water and Sanitation District**

### **North Well**

- The North Tank drain was opened briefly to expel any accumulated solids in the bottom of the tank.
- Well was turned off to facilitate the tank draining through normal usage to prepare and tank drained for work on tank. The tank was not able to be drained completely due to the low level pump cutoff in the tank.
- The drain line for the tank does not daylight. When the remainder of the tank was drained, it cut a trench down the road to the North Well. It also flooded the neighborhood to the East and made a mess of some landscaping at 9780 Hi-Land Cir.
- Welgicide cleaner application has been ordered and will be scheduled as the vendors time allows.
- ORC has reached out to Water Systems Engineering for a cost proposal to investigate the North Well and provide a report similar to that of Twin Lake Estates. We will pass on the estimate when it arrives.

### **South Well**

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- With North well turned off, the South well is handling all distribution usage needs.

### **Distribution System**

- Normal operations
- Bacteriological sampling collected and passed.