

**ORC Water Professionals**

**Operations Report**

**Dec 2022**

**Prepared by: Gabrielle Begeman and Jake Ward**

### **Hi-Land Acres Water and Sanitation District**

#### **North Well**

- The North Tank is still drained awaiting the completion of the welgicide application to refill from the North Well.
- Welgicide cleaner has been received by the vendor and will be scheduled in the coming months.

#### **South Well**

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- With North well turned off, the South well is handling all distribution usage needs.

#### **Distribution System**

- Normal operations
- Bacteriological sampling collected and passed.
- Valve exercising has begun, will be completed in the next few weeks, weather permitting.