

ORC Water Professionals

Operations Report

Feb 2023

Prepared by: Gabrielle Begeman and Jake Ward

Hi-Land Acres Water and Sanitation District

North Well

- North well is not in use currently
- Will be flushing the well and getting the north side ready for operation in the following month

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- With North well turned off, the South well is handling all distribution usage needs.

Distribution System

- Normal operations
- Bacteriological sampling collected and passed.
- Valve exercising is complete
- Each meter pit should be receiving frost guards if not already installed. During this process the operator will make the meter lids accessible once found.