

## **Hi-Land Acres Water and Sanitation District**

### **North Well**

- North well is not in use currently.
- The tank is full of water that was brought over from the south well through the distribution system. This water was re-chlorinated before entering the tank.
- Both booster pumps have been reinstalled into the North well.

### **South Well**

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- With North well turned off, the South well is handling all distribution usage needs.

### **Distribution System**

- Normal operations
- Bacteriological sampling collected and passed.