

Hi-Land Acres Water and Sanitation District

North Well

- North tank is still in use currently. Being filled with water and chlorinated from the south well.
- All systems are operating well and rotating on different days between the north system and the south system.

South Well

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- Still handling the flow needed to fill the north tank with no problems.

Distribution System

- We have worked with the metering company to get the most accurate readings for water usage. From now on we should get the best numbers for billing purposes.