

### **Hi-Land Acres Water and Sanitation District**

#### **North Well**

- North tank is still in use currently. Being filled with water and chlorinated from the south well.
- All systems are operating well and rotating on different days between the north system and the south system.

#### **South Well**

- Normal operation without any difficulties.
- Tank level within normal range for the month.
- Still handling the flow needed to fill the north tank with no problems.

#### **Distribution System**

- All valves were exercised throughout the district.