

Hi-Land Acres Water and Sanitation District

North Well

- North tank is still in use currently. Being filled with water and chlorinated from the south well.
- Tank is not filling well when distribution pumps are running. A timer has been installed to fill the tank on days that the booster pump is not running.

South Well

- Normal operation without any difficulties.
- Tank level has begun to decline to approximately half of capacity this month with all usage coming from the South.

Distribution System

- The meter reading equipment has failed and meters have been estimated again for this month.
- Weather is hot and usage is greater than the amount of water the South well can produce.