

Hi-Land Acres Water and Sanitation District

North Well

- North tank is still in use currently. Being filled with water and chlorinated from the south well.
- Tank fills partially on days booster pumps are not in use. Then emptied on days when booster pumps are in use.
- Low tank levels are suppressing the booster pumps from running.

South Well

- Normal operation without any difficulties.
- Tank level has not been above half capacity this month.

Distribution System

- The meter reading equipment has failed and meters have been estimated again for this month.
- Weather is hot and usage is greater than the amount of water the South well can produce.