

## **Hi-Land Acres Water and Sanitation District**

### **North Well**

- All systems running well.

### **South Well**

- Welded South Tank has shown leaking at the base of the tank. We have been in communication with Colema and they plan to revisit the tank and weld the leak closed. They are not in town and will complete the work when they come back scheduled for July.

### **Distribution System**

- Meter reads completed