

ORC Water Professionals
Operations Report
September 2025
Prepared by: Gabrielle Begeman and Tim Schneider

Hi-Land Acres Water and Sanitation District

North Well

- North well operational normally

South Well

- Leaking pipe received an epoxy coating to repair cracks/holes. Tank sealed and refilled.
- Pipe coating did not take. Tank is continuing to leak.

Distribution System

- Meter reads completed