

ORC Water Professionals

Operations Report

Feb 2026

Prepared by: Gabrielle Begeman and Tim Schneider

Hi-Land Acres Water and Sanitation District

North Well

- System running well

South Well

- South Well Shut down for a few days to collect parts and repair chemical dosing pump.
Repair was completed and the system was restored

Distribution System

- Meter reads collected