

Hi-Land Acres Water and Sanitation District

North Well

- System running well

South Well

- Further investigation into leaking tank. Additional damage was discovered. Preparation work has started to apply additional lining around area of leak.
- Pump house cleaning and reorganizing. Cardboard boxes were replaced with containers. All maps/ paper stored inside containers.

Distribution System

- Meter reads collected
- Leak identified at 15740 Elmira St.