

Hi-Land Acres Water and Sanitation District

North Well

- All systems running well

South Well

- South welded tank successfully fixed with the fourth patch to the incoming piping.
- The tank was cleaned and put back online.

Distribution System

- Meter reads completed
- A massive leak was found on the master service line that runs to the homes on Yosemite. This meter service was isolated on May 1st to prevent a loss of water to all residents.
- The homeowners fixed the line and service was restored on May 22.